

The results (column H) are reported in mg/l or parts per million. The action level for lead is any result greater than 0.015 mg/l. The action level for copper is any result greater than 1.3 mg/l. "ND" stands for non-detect: the contaminant was not detected above the MDL.

CITY/TOWN	ORG CODE	SCHOOL NAME	LOCATION ID	SAMPLE LOCATION NAME	SAMPLE COMMENTS	ANALYTE NAME	RESULT	UNITS OF MEASUREMENT	METHOD DETECTION LIMIT	ANALYSIS LAB	LAB SAMPLE ID	SAMPLER NAME	SAMPLE COLLECTION DATE	SAMPLE COLLECTION TIME	REPORT DATE
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	001F	Basement Girls Room Bubbler/Left-F	DW	LEAD	ND	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 2	RJ	9/23/2016	06:29:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	001F	Basement Girls Room Bubbler/Left-F	DW	COPPER	0.009	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 2	RJ	9/23/2016	06:29:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	001P	Basement Girls Room Bubbler/Left-P	DW	LEAD	0.006	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 1	RJ	9/23/2016	06:28:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	001P	Basement Girls Room Bubbler/Left-P	DW	COPPER	0.041	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 1	RJ	9/23/2016	06:28:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	002P	Basement Girls Room Bubbler/Right0P	DW	LEAD	ND	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 3	RJ	9/23/2016	06:28:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	002P	Basement Girls Room Bubbler/Right0P	DW	COPPER	0.038	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 3	RJ	9/23/2016	06:28:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	003F	Kitchen Dish Sink-F	KC	LEAD	ND	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 5	RJ	9/23/2016	06:32:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	003F	Kitchen Dish Sink-F	KC	COPPER	0.006	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 5	RJ	9/23/2016	06:32:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	003P	Kitchen Dish Sink-P	KC	LEAD	ND	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 4	RJ	9/23/2016	06:31:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	003P	Kitchen Dish Sink-P	KC	COPPER	0.034	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 4	RJ	9/23/2016	06:31:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	004F	Basement Boys Room Bubbler/Left-F	DW	LEAD	ND	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 7	RJ	9/23/2016	06:34:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	004F	Basement Boys Room Bubbler/Left-F	DW	COPPER	0.023	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 7	RJ	9/23/2016	06:34:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	004P	Basement Boys Room Bubbler/Left-P	DW	LEAD	0.002	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 6	RJ	9/23/2016	06:33:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	004P	Basement Boys Room Bubbler/Left-P	DW	COPPER	0.063	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 6	RJ	9/23/2016	06:33:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	005P	Basement Boys Room Bubbler/Right-P	DW	LEAD	0.008	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 8	RJ	9/23/2016	06:33:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	005P	Basement Boys Room Bubbler/Right-P	DW	COPPER	0.081	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 8	RJ	9/23/2016	06:33:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	006F	1st Floor Bubbler Outside Main Office-F	DW	LEAD	0.002	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 10	RJ	9/23/2016	06:36:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	006F	1st Floor Bubbler Outside Main Office-F	DW	COPPER	0.01	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 10	RJ	9/23/2016	06:36:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	006P	1st Floor Bubbler Outside Main Office-P	DW	LEAD	0.011	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 9	RJ	9/23/2016	06:35:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	006P	1st Floor Bubbler Outside Main Office-P	DW	COPPER	0.032	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 9	RJ	9/23/2016	06:35:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	007F	Nurse Room Sink-F	NS	LEAD	0.001	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 12	RJ	9/23/2016	06:40:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	007F	Nurse Room Sink-F	NS	COPPER	0.007	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 12	RJ	9/23/2016	06:40:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	007P	Nurse Room Sink-P	NS	LEAD	0.034	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 11	RJ	9/23/2016	06:40:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	007P	Nurse Room Sink-P	NS	COPPER	0.024	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 11	RJ	9/23/2016	06:40:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	008F	Teacher's Room Sink-F	CF	LEAD	ND	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 14	RJ	9/23/2016	06:43:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	008F	Teacher's Room Sink-F	CF	COPPER	0.032	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 14	RJ	9/23/2016	06:43:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	008P	Teacher's Room Sink-P	CF	LEAD	0.007	MG/L	0.001	NASHOBA ANALYTICAL LLC	170905 13	RJ	9/23/2016	06:42:00	27-Sep-16
Lawrence	01490001	Lawrence: Rollins Early Childhood Center	008P	Teacher's Room Sink-P	CF	COPPER	0.051	MG/L	0.003	NASHOBA ANALYTICAL LLC	170905 13	RJ	9/23/2016	06:42:00	27-Sep-16