

The results (column H) are reported in mg/l or parts per million. The action level for lead is any result greater than 0.015 mg/l. The action level for copper is any result greater than 1.3 mg/l. "ND" stands for non-detect: the contaminant was not detected above the MDL.

CITY TOWN	ORG CODE	SCHOOL NAME	LOCATION ID	SAMPLE LOCATION NAME	SAMPLE COMMENTS	ANALYTE NAME	RESULT	UNITS OF MEASUREMENT	METHOD DETECTION LIMIT	ANALYTICAL METHOD USED	ANALYSIS LAB	LAB SAMPLE ID	SAMPLER NAME	SAMPLE COLLECTION DATE	SAMPLE COLLECTION TIME	REPORT DATE
Lawrence	01490040	Lawrence: Francis M Leahy	002F	Bubbler Outside Room 101-F	DW	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 2	RJ	9/21/2016	06:57:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	002F	Bubbler Outside Room 101-F	DW	COPPER	0.005	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 2	RJ	9/21/2016	06:57:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	002P	Bubbler Outside Room 101-P	DW	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 1	RJ	9/21/2016	06:56:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	002P	Bubbler Outside Room 101-P	DW	COPPER	0.018	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 1	RJ	9/21/2016	06:56:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	003F	Bubbler Outside Room 201-F	DW	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 4	RJ	9/21/2016	07:06:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	003F	Bubbler Outside Room 201-F	DW	COPPER	0.003	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 4	RJ	9/21/2016	07:06:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	003P	Bubbler Outside Room 201-P	DW	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 3	RJ	9/21/2016	07:05:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	003P	Bubbler Outside Room 201-P	DW	COPPER	0.007	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 3	RJ	9/21/2016	07:05:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	004F	Nurse Room Sink-F	NS	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 6	RJ	9/21/2016	07:07:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	004F	Nurse Room Sink-F	NS	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 6	RJ	9/21/2016	07:07:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	004P	Nurse Room Sink-P	NS	LEAD	0.001	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 5	RJ	9/21/2016	07:06:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	004P	Nurse Room Sink-P	NS	COPPER	0.018	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 5	RJ	9/21/2016	07:06:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	005F	Teacher's Room Sink/2nd Floor-F	CF	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 8	RJ	9/21/2016	07:03:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	005F	Teacher's Room Sink/2nd Floor-F	CF	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 8	RJ	9/21/2016	07:03:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	005P	Teacher's Room Sink/2nd Floor-P	CF	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 7	RJ	9/21/2016	07:02:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	005P	Teacher's Room Sink/2nd Floor-P	CF	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 7	RJ	9/21/2016	07:02:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	006F	Bubbler Outside Room 209-F	DW	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 10	RJ	9/21/2016	07:01:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	006F	Bubbler Outside Room 209-F	DW	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 10	RJ	9/21/2016	07:01:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	006P	Bubbler Outside Room 209-P	DW	LEAD	0.002	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 9	RJ	9/21/2016	07:00:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	006P	Bubbler Outside Room 209-P	DW	COPPER	0.012	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 9	RJ	9/21/2016	07:00:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	009F	Basement Behavior Support Sink/Bas-F	OT	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 12	RJ	9/21/2016	07:17:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	009F	Basement Behavior Support Sink/Bas-F	OT	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 12	RJ	9/21/2016	07:17:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	009P	Basement Behavior Support Sink/Bas-P	OT	LEAD	0.003	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 11	RJ	9/21/2016	07:16:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	009P	Basement Behavior Support Sink/Bas-P	OT	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 11	RJ	9/21/2016	07:16:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	010F	Library Sink-F	OT	LEAD	ND	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 14	RJ	9/21/2016	07:12:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	010F	Library Sink-F	OT	COPPER	ND	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 14	RJ	9/21/2016	07:12:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	010P	Library Sink-P	OT	LEAD	0.002	MG/L	0.001	SM 3113B	NASHOBA ANALYTICAL LLC	170907 13	RJ	9/21/2016	07:11:00	27-Sep-16
Lawrence	01490040	Lawrence: Francis M Leahy	010P	Library Sink-P	OT	COPPER	0.025	MG/L	0.003	EPA 200.7	NASHOBA ANALYTICAL LLC	170907 13	RJ	9/21/2016	07:11:00	27-Sep-16